

Phone: 916-786-3800 Fax:

916-786-8905

www.pasco.com

ISO 9001 Certified

PS-3209; Wireless Weather Sensor Battery Replacement Instructions

Battery part number PS-3295; BATT LI 3.7V 1000mAH or PS-3294; BATT LI 3.7V 1000mAH Recommended Equipment: (PS-3299; Battery Replacement Tool Set)







Torx T5 Driver

PS-3295

or PS-3294 (B version)**

**Note: Check the back side of the plastic enclosure of the PS-3200 you are using. If there is a "B" in the printing as shown below, then the replacement battery model number is PS-3294. If there is no "B" on the printing, the replacement battery is PS-3295.

> Model: PS-3209 Designed by PASCO in California Assembled in China **(I**(CCAN22Y10160T2 FCC ID: YAIBM10R3 IC: 20480-BM10R3 R 020-220039





CAUTION: Failure to use proper ESD protection could result in damage to the electronics.



Use Electrostatic Discharge Protective Handling Procedures.

PASCO Form Number	Description	Date		Revision
013-16107	PS-3209 Battery Replacement Instructions	11-29-22	Page 1 of 4	С



Phone: 916-786-3800 Fax: 916-786-8905

916-786-8905 www.pasco.com

ISO 9001 Certified

Step 1: Position the Sensor on a surface as shown. Note the quantity of the (9) Torx T5 Screws (circled).



Step 2: Unscrew and remove the 9 Torx Screws with the T5 Screwdriver.



Step 3: While holding both halves together, flip the product over looking at the front surface as shown.



PASCO Form Number	Description	Date		Revision
013-16107	PS-3209 Battery Replacement Instructions	11-29-22	Page 2 of 4	С




Phone: 916-786-3800 Fax: 916-786-8905

916-786-8905 www.pasco.com

ISO 9001 Certified

Step 4: While holding the bottom with one hand, lift and rotate the top cover to the right as shown.





Step 5: Remove the battery strap screws (2) with the T5 Screwdriver and remove the battery strap. Unplug the battery from its connector. Remove the battery and add the replacement battery at the location shown (see above picture) and position the wiring similar to the routing shown above. Plug the battery into its mating connector and reverse the steps noted above to complete the reassembly.

PASCO Form Number	Description	Date		Revision
013-16107	PS-3209 Battery Replacement Instructions	11-29-22	Page 3 of 4	С



Phone: 916-786-3800 Fax: 916-786-8905

www.pasco.com



ISO 9001 Certified

Batteries contain chemicals that, if released, may affect the environment and human health. Batteries should be collected separately for recycling, and recycled at a local hazardous material disposal location adhering to your country and local government regulations. To find a battery recycling drop-off location, please contact local waste disposal service or the product representative.



The battery or batteries used in PASCO products are marked with the European Union symbol for waste batteries (above) to indicate the need for separate collection and recycling. For small batteries, the symbol is printed on the packaging.



If you need further assistance, please contact Technical Support at support@pasco.com or through www.pasco.com on chat. To access chat through your browser, please enable all cookies on our website.

PASCO Form Number	Description	Date		Revision
013-16107	PS-3209 Battery Replacement Instructions	11-29-22	Page 4 of 4	С